



U.S. DEPARTMENT OF ENERGY

WHAT DOES DECOMMISSIONING INVOLVE ?

Decontamination and Decommissioning Facilities



- Three separate process buildings (X-326, X-330, X-333) total 96 acres (about 200 football fields of floor space under roof). If these buildings are removed, these steps would be taken.
 - Remove hazardous material such as lubricating oils and mercury switches
 - Dismantle and remove the radiologically contaminated process equipment
 - Remove asbestos within the buildings
 - Deactivate the utilities (heat, light, water)
 - Remove exterior asbestos siding
 - Demolish the structure
- Plant support facilities that are no longer needed will be removed.
- Utilities (steam, power, and water) must be altered and optimized to support other site tenants (American Centrifuge Project and Uranium Disposition Services).



OUR SITE.
OUR FUTURE.

